

John Grace Arms – 10/20/2025- Bulletin 5 Changes

Summary of Structural Changes:

- S000
 - Updated index.
- S004
 - Updated SW3 in wood shear wall schedule to 2x4 DFL studs.
 - Removed continuous footing schedule.
- S100-A
 - Included continuous footing schedule.
- S100-E
 - Included notes and references to continuous footing schedule on sheet S100-A.